### RCRA FACILITY ASSESSMENT EVALUATION

### PRELIMINARY REVIEW, VISUAL SITE INSPECTION

## AND SAMPLING VISIT

Region 6, RCRA Permits Closure Section

FACILITY'S NAME(S):	American Chrome	& Chemicals, Inc			
IPA 10 MURBER: TX0098018339					
AUDRESS:	ANDRESS: P. O. Box 9912				
LOCATION:	Buddy Lawrence D	rive, Corpus Chr	isti		
DATE OF INSPECTION:	July 20-21, 1997				
SITE DESCRIPTION:					
PREPARED DY: Pope-R	eid Associates	DATE PREPARED:	August 1987		
REVIEWED BY: K. N.	Phillips/Y. Kim	DATE REVIEWED:	July 1989		
FACILITY STATUS: LD	-Closure				
ANTICIPATED PERMIT D	ATE:	CLOSURE PLAN AP	PROVED DATE:		
ANY ON-GOING STATE/F	ED 264, 265, or 2	70 CORRECTIVE AC	TION OR CERCLA		
DOES FACILITY HAVE A	CERCLA FILE? YE	s <u>x</u> to			
then was a CERCLA PA	/SI performed at	this facility:	4/22/85		
DUES FACILITY HAVE U	IC WELL? YES	110 <u>X</u>	TYPE N/A		
TYPE OF DRINKING NAT	ER SUPPLY WITHIN	A 3-MILE RADIUS:	59 (Inland Reservoir)		
TARGET POPULATION WI	THIN A 3-MILE RAD	198: 4,000 est.			
RECOMMENDATIONS:	SV X IH X	RFI No RFI			
(In	dicate only one u	nless IH is mark	ed)		
	<u>Permit: X 3004</u>	(u)3004(v)			
Possible	Enforcement Action	n:3908(a) _	3098(h)		

29 (1) (1) (1) (1) (1)

Form Rev. 9/1/88 LB:qjj:9/1/89



180029

### I. EVALUATION

Λ. NUMBER OF SUHU(s)/ΛΟC(s) INVESTIGATED DURING THE PR/VSI: 53

•			
	1. NUMBER OF SHMU(s) INVESTIGATED I	DURING THE PR/VSI:	51
<del>ù</del>	LIST OF SWIND	REGULATED BY RCRA*	STATUS**
1.	Waste Monoethanolamine Tank	?	A
2.	Waste Mud tank	?	A
3.	Residue Surge Tank	?	Α
4.	Residue liead Tank	?	Α
5-3.	Residue Treatment Tanks	?	Λ
9-11.	Secondary Treatment Tanks	?	Ä
12.	Surface Drainage Tank		Ä
13.	Waste Cil Tank	N	Î
	Chromic Acid Plant Cooling Tower Basir		A
16-13.	Chromic Plant Cooling Tower Basins	N	۸
19.	Power Plant Cooling Tower Basin	H	Α
20.	Chromic Oxide Process	H	Λ
21.	Chromic Acid Plant Settling Basin	N	Α
22.	West Pond	N	Α
23.	Middle Pond	N	Α
24.	East Pond	N	А
25.	No. 6 Sump Area	N	A
26.	No. 9 Sump Area	N	Ā
27.	Settling Basin	Ñ	Ä
		N	Ĩ
28.	Haste Area No. 1		
29.	170 • 6	i4	I
30.	110 • 3	N	Ī
31.	" " No. 4	N	I
32.	" No. 5	N	I
33.	" No. 6	. 14	A
34.	" Ho. 7	N	I
35.	" No. 8	N	I
36.	Asbestos Landfill	N	I
37.	Soda Ash Solids Deposition Area	N	1
38.	Waste Refactory Material Storage Area	N	Ī
39	PCB and Asbestos Storage Area	il	Ā
	Contaminated Refuse Roll-Off Bin	N	Â
40.		N	Ä .
41. 42.	Waste Trays Trash Dumpsters	14 []	Ä
43.	Chromate Plant Process Sewers and Sump		Ą
	·		Ä
44.	Chromium Processing Area Stormwater Se		
45.	Chromic Acid Plant Drains and Sumps	ii	V
46.	Piping to Haste Areas	N	Ÿ
47.	Chromic Oxide Process Wastewater Pipir		A
48-50.	Chromate Plant Filter Presses	N	A
51.	Sea Hater Flume	N	Α

### 2. AREAS OF CONCERN:

## LIST OF AOC

- Chromate Plant Area (AOC "A")
   Oil Leakage Area (AOC "B")

<sup>\*</sup> Y-Yes, N-No, (?) Uncertain \*\* Λ-Active, I-Inactive, C-Closed

## B. SAMPLING VISIT (See the Sampling Visit Report for details)

SWMU OR AOC SAMPLING LOCATION	SAMPLE/MEDIA SAMPLE TYPE (GRAB. COMPOSITE)	PARAMETERS	RESULTS OF MOST PREVA CONSTITUENTS (mg/k	
Sample 001 SWNU #20 Chromic Oxide Process Wastewater Tank	Soil/Grab	Metals:	Chromium Lead Zinc	4774 73 472
	·	Volatile	Trimethylethylbenzene	0.28
		Semi-volatile	Acenaphthlene Fluorene Phenanthrene Benzo(a) Authracene Bis-(2-ethylhexyl) Phthalate Benzo(a) Pyrene	0.30 0.37 21.60 43.80 43.8 20.3

## 8. SAMPLING VISIT (See the Sampling Visit Report for details) - continued

SMMU OR AOC SAMPLING LOCATION	SAMPLE/MEDIA SAMPLE TYPE (GRAB. COMPOSITE)	PARAMETERS	RESULTS OF MOST PREVALENT CONSTITUENTS (mg/KG)	
Sample 002 SWMU #27 Settling Basin	Soil/Grab	Metals:	Selenium Chromium 126 Copper 2 Lead 16	23 1 54 25 56 32
		Volatile	No data available from the analysis in Appendix E	<b>1</b>
	·	Semi-volatile	No data available from the analysis in Appendix E	·
	·			

## B. <u>SAMPLING VISIT</u> (See the Sampling Visit Report for details) - continued

SWMU OR AOC SAMPLING LOCATION	SAMPLE/MEDIA SAMPLE TYPE (GRAB. COMPOSITE)	PARAMETERS -	RESULTS OF MOST PREVALENT CONSTITUENTS (mg/KG)	
Sample #903 Background	Soil/Grab	Metals	Arsenic Mercury Chromium Copper Lead Nickel Zinc	3 0.68 56 86 360 253 1053
		Volatile	N. D.	
		Semi-volatile	Fluoranthene Pyrene Bis - (2-ethylhexyl) Phthalate	0.16 0.12 2.5

- C. NUMBER OF SWMU(s)/AOC(s) FOR WHICH AN RFI IS RECOMMENDED: 24 / 2 (Except RCRA units subject to Subpart F groundwater issues refer to Section D)
  - 1. NUMBER OF SWMU(s)/AOC(s) AT WHICH RELEASES HAVE BEEN IDENTIFIED: 5 / 1

SWMU/AOC NO.	RELEASE TO	NOTED DOCUMENTATION OF RELEASE
1. Chromic Oxide, Process Wastewater Tank (SWMU #20)	Soil/GW	During the VSI, stained soil, stressed vegetation, and an oily residue covering portions of the area around the tank were observed. Data from sampling visit indicate that soil underneath the tank was contaminated by chromium 4774 mg/kg.
2. Settling Basin (SWMU #27)	Soi 1/GW	Results from the sampling visit confirms the unit receives hazardous constituents, (I.B., this report, and Table 3-2 of SV report). The unit is an unlined surface impoundment. The impact of this unit on the current GW contamination problem has yet to be clarified. soil sample indicates arsenic (28mg/kg), chromium (1264 mg/kg), lead (106 mg/kg), etc. contamination.
3. Waste Area No. 2 (SWMU #29)	Soil/GW	Through investigations conducted by the TWC, this unit has been identified as one of the primary sources of chromium GW contamination. Unit is unlined with clay soil dikes that have become eroded in places (Ref. Dames and Moore, Hydrological Studies and Investigation of Cr <sup>6+</sup> Jan. 1982).
4. Waste Area No. 5 (SWMU #32)	Soil/GW	This unit was found to be a source of run-off containing hexavalent chromium in a TWC investigation (Ref. Dames and Moore, Hydrological Studies and Investigation of Cr <sup>6+</sup> Jan. 1982).  During the VSI, a greenish stain was observed on the dike/road as well as in the ditch outside the containment dikes of the unit. Unit was only partially covered with soil and sparse vegetation.

(_{_{1}}, _{_{2}}, _{_{3}}, _{_{4}})	OYAN, 190.	pelane to	NOTED DOCUMENTATION OF RELEASE
<b>*</b> •	Chroatne Plant Process Seners and Sums (Sent) #83)	Rof 1/64	The unit has been identified as one source of chromius GV contamination to the plant area (Ref. Pope-Byta Associates, July 33 and 21, 1987, VSI Leybooks). At the time of the VSI, corrective measures had not been taken to stop further releases.
	Oremate Plant Orea (A)() Ty*)	3 <b>011/</b> 58	THE new identified the Chromate Flant area as a source of extensive ground water contamination (Ref. Hydrological Studies and lovestigation of Crot Jan. 1982). Concentration of chromium is as high as 4000 kg/l. Concentrations in the GV of this area have not been reduced in 5 years.

## 2. MERGER OF SEMEX/ROCK AT WHICH A RELEASE IS RIGHLY POSSIBLE: 15 / 1

LIST OF SHOP	MENIA	CATIONALE/CONCERN
1. Power Plant Cooling Tower Casto ((SWES \$19)	Sail/GR	Suring the VSI, the visible nortion of the basis was corroled and spillage was evident on the outside of the basis walks. The spillage presumably went unto the unit.
2-4. Gess, Hiddle and Cast Ponds (SHMUS 322-24)	3e11/6#	The units are located to on area where groundwater is containated by hexavalent chromium. The units also are identified as the source of sulfidic edors. The units are unlined surface impoundments which receive wastewater containing trivalent and hexavalent caroaium. Dikes of the impoundments are constructed of sull and high-live chromats residue.
A. Susp Ares Me. 6 (INAU 225)	\$911/34	The sumu was not visible during the USI because it was submerced. The pump for the sump was incommative. The unit is in an area where groundwater is contactioated with herevalent chromium. Good vegetation was present at the warpin of the unit.
C. Shong Area on. 7 (Sant ben)	2441/6#	During the 951, leachate was present outside the 11ke west of the unit. Deed vegetation was present at the swep area margins. The point is located to an area where groundwater is contacted.

SUMU/AOC NO.	RELEASE TO	HOTED DOCUMENTATION OF RELEASE
7. Waste Area No. 1 (SWMU #28)	So11/GW	The unit is unlined and uncapped. At the time of the VSI, the unit received chromate high-lime residue and bad reaction batches of off-spec sodium chromate and sodium dichromate. The highest chromium level in the GW is approximately 500 feet downgradient from the unit. During the VSI, water tinted blue was observed in shallow depressions north and east of the unit. Dikes for the unit were severely eroded. Runoff from this unit is poorly contained and allowed to flow indiscriminately to the east and north.
3. Waste Area No. 3 (SWMU #30)	Soi 1/GW	The unit is in an area where chromium-contaminated GN has been found by TWC. The unit may have a liner, but no documentation is available. Dikes are clay soil.
9. Waste Area No. 4 (SWMU #31)	Soi 1/GW	The unit is unlined and has received chromate high-lime residue which was only partially treated to reduce the hexavalent chromium. The unit is located in an area with chromium contaminated GW.
10. Waste Arda No. (SHMU #33)	6 Soft/GW	The unit is an unlined surface impoundment which has received high-lime chromate. Unit is located in an area with chromium contaminated GW. During the VSI, ponding of runoff was observed in contact with chromium wastes, which is conducive to leachate generation. It was observed during the VSI that a portion of the waste area had been diked and residues were being actively deposited within the diked areas. The west and south ends were flooded by water in the No. 6 Sump area (SNMU #25).
11. Waste Area No. (SWAU #34)		The unit is an unlined surface impoundment. The unit has received high-lime chromate residue and is located in an area where the GW is contaminated with hexavalent chromium. During the VSI, greenish-blue water and leachate deposits were observed outside of a ditch on the west and south sides of the unit.

SWA	/AOC NO.	HEDIA	RATIONALE/CONCERN
12.	Waste Area No. 8 (SMMU #35)	Set 1/GV	The unit was originally an unlined surface impoundment. It now has the appearance of a landfill. The unit received high-lime chromate residue. During the VSI, extensive greenish-blue staining outside of the soil dikes along the northern margin of the area was observed. The area within 150 feet of the northern boundary of the unit was devoid of vegetation. The unit is in an area where GH is contaminated with hexavalent chromium.
13.	Soda Ash Solids Deposition Area (SWAU #37)	Sot 1/GN	The unit is an unlined landfill. Hazardous constituents were deposited in this area. During the VSI it was noted that much of the area was previously covered by substantial vegetation.
14.	Waste Refactory Material Storage (SWMU #33)	So11/GW	The unit is an asphalt pad, on which refactory material contaminated with hexavalent chromium is piled for temporary storage. Run-off is not contained or controlled and is allowed to drain directly to surrounding soil prior to reaching stormwater sewer system.
15.	Piping to Waste Areas (SWHU #46)	So11	The piping appeared unmaintained, corroded, in poor condition, and is located on unpaved soil over most of its length.
16.	011 Leakage Area (AOC "B")	Sof 1/GH	An underground pipe is leaking oil. During the VSI, soil heavily stained with oil and yellow deposits was observed. This leak has been occurring since 1960. The amount of seepage has decreased in the last 2 years, possibly indicating the migration pathway may have been altered by GM Pump and Treat programs. Facility representatives stated they had never tried to find the exact source of the leakage.

# 3. MUMBER OF SUMU(s)/AOC(s) WHERE A DETERMINATION CANNOT BE MADE DUE TO LACK OF INFORMATION: 4-/ 0

#### LIST OF SWMU

- 1-3. Chromate Plant Cooling Tower Basins (SWAU #16-18)
- 4. Asbestos Landfill (SWMU #35)

### RATIONALE

The integrity of basin is unknown. The basins are over twenty years old and a release potential exists if cracks or holes are present.

The unit is an unlined landfill. It has received asbestos diaphragm cells and other asbestos wastes from the Chlor-Alkali plant. Chlorinated organics could have been disposed of with the asbestos waste.

D. NUMBER OF SWMU(s)/AOC(s) FOR WHICH AN RFI IS NOT RECOMMENDED: 27 / 0

#### LIST OF SWMU

#### RATIONALE

 Waste Monoethanolamine Tank (SWMU #1) The unit is above-ground on a concrete paved area. No evidence of release was observed during the VSI.

2. Waste Mud Tank (SWMU #2)

This tank is above-ground in good condition. No evidence of release was observed during the VSI.

3. Residue Surge Tank (SWMU #3)

The unit is located on a concrete pad and appeared to be in good condition. No evidence of release was observed during the VSI.

4. Residue Head Tank (SWMU #4)

The unit is an above-ground and closed-topped tank. No evidence of release was observed during the VSI.

5. Residue Treatment Tanks (SWMU #5-11) The units are closed-topped and above-ground tanks. No evidence of release was observed during the VSI.

6-8. Secondary Treatment Tanks (SWMUs #9-11) The units are on-ground and open-topped tanks with concrete foundations. No evidence of release was observed during the VSI.

9. Surface Drainage Tank (SWMU #12) The unit is a closed-topped and above-ground steel tank. No evidence of release was observed during the VSI.

10. Waste Oil Tank (SWMU #13) The unit is a closed-topped and above-ground steel tank. No evidence of release was observed during the VSI.

11-12. Chromic Acid Plant Cooling Tower Basin (SWMUS #14-15) The basins were recently built (in 1984). No evidence of release was found during the VSI.

13-15. Chromate Plant Cooling Tower Basins (SWMUs #16-18) The units are below-ground concrete basins. No evidence of release was observed during the VSI.

16. Chromic Acid Plant Settling Tank (SWMU #21) The unit was recently built on a concrete-paved area and is an above-ground and closed-topped tank. No evidence of release was observed during the VSI.

17. PCB and Asbestos Storage Areas (SWMU #39) The unit is in an enclosed building with a concrete floor. No evidence of release was observed during the VSI.

18. Contaminated Refuse Roll-off Bin (SWMU #40) The unit is a steel bin resting on a concrete pad. No evidence of release was observed during the VSI.

19. Waste Trays (SWMU #41)

The units are constructed of metal and open topped. No evidence of release was observed during the VSI.

20. Trash Dumpsters (SWMU #42)

The units are steel bins. No evidence of release was observed during the VSI.

21. Chromium Processing Area Stormwater Sewers (SWMU #44) The unit consists of drains, sumps and underground piping. No evidence of releases were proven at the time of the VSI.

22. Chromic Acid Plant Drains and Sumps (SWMU #45) The unit consists of drains and sumps. Waste is pumped to the settling tank. No evidence of release was observed during the VSI.

23. Chromic Oxide Process
Wastewater Piping
(SWMU #47)

The units consist of on-ground steel and flexible hose piping. No evidence of release was observed during the VSI.

24-26. Chromate Plant: Filter Presses (SWNUs #48-50) The units are located in a metal structure on a platform above a paved area. No evidence of release was observed during the VSI.

27. Sea Water Flume (SWMU #51)

The unit consists of a concrete ditch and concrete piping. The ditch is above-ground and the piping is underground. No evidence of release was observed during the VSI.

E. SUPPLEMENTAL INFORMATION ON RCRA REGULATED UNITS: 0
(Describe any additional problems identified or suspected from regulated units including identified releases to groundwater.)

#### II. FINDINGS

#### A. RECOMMENDATIONS:

- 1) Contractor: (1) No further action for twenty-eight (28) SWMUs. SWMU Nos. are 1-8, 13-15, 21, 28-35, 39-42, and 47-50.
  - (2) Suggested Actions for twenty-one(21) SWMUs and two (2) Areas of Concern: SWMU Nos. are 9-12, 16-19, 22-20, 36-38, 43-46 and 51. The actions are (a) to determine the integrity of the unit, (b) pressure test, (c) to verify regulatory status, (d) to construct a secondary containment, (e) soil sampling, (f) to continue with closure, etc.
  - (3) RFI for two (2) units: SWAU Nos. 20 and 27.
- EPA: Recommends an RFI for twenty-four (24) SWMUs and two
   Areas of Concern in Section C of this evaluation.

### 9. ADDITIONAL COMMENTS:

- 1) The facility is presently undergoing a Pump and Treat program for GM contamination. The GW contamination is extensive and over the past five years the corrective measures taken have done little or nothing to improve the situation.
- 2) Regulatory status of SMMUs 1-12 is uncertain due to a temporary exclusion for the KOO6 wastes at the facility. The exclusion was ultimately denied November 14, 1986. However, the facility is still storing hazardous KOO6 wastes on site and commingling nonhazardous wastes with existing hazardous waste. (See memo dated on Feb.1988, Regulatory Status; to file.)

CONCUR: Bill Luthans	DATE:	7/28/89
----------------------	-------	---------